

Table 1B
Post-Remedial Radon Sample Collection and Analytical Results Summary Table
Canadian Radium and Uranium Site
Kisco Avenue, Mount Kisco, New York

RST 3 Sample No.	Canister Serial No.	Results (pCi/L)	Std. Dev. (pCi/L)	Start		Stop		Sample Type	Floor	Location
				Date	Time	Date	Time			
Property C003 - 105 Kisco Avenue										
C003-AAP008-01	2430479	1.0	+/- 0.2	10/23/2015	11:08	10/26/2015	11:24	Field Sample	Ground	Main Building, Showroom #1, 16.6' West from NE corner on top of a shelf
C003-AAP009-01	2430415	0.9	+/- 0.2	10/23/2015	11:12	10/26/2015	11:26	Field Sample	Ground	Main Building, Showroom #1, 4' from North wall and 2' from South wall on PEI stand
C003-AAP010-01	2430417	0.6	+/- 0.2	10/23/2015	11:15	10/26/2015	11:29	Field Sample	Ground	Main Building, Showroom #2, Middle of the room on a PEI stand
C003-AAP011-01	2430547	1.0	+/- 0.2	10/23/2015	11:30	10/26/2015	11:31	Field Sample	Ground	Main Building, Showroom #2, 9.3' West from NE corner on a PEI stand
C003-AAP012-01	2430403	1.0	+/- 0.2	10/23/2015	11:33	10/26/2015	11:38	Field Sample	Ground	Main Building, Showroom #3, 10.8' West, 14' South from NE corner on PEI stand
C003-AAP013-01	2430464	2.0	+/- 0.2	10/23/2015	11:36	10/26/2015	11:40	Field Sample	Ground	Main Building, Showroom #3, 18.3' North, 4.4' West from SE corner of a shelf
C003-AAP014-01	2430466	1.4	+/- 0.2	10/23/2015	10:56	10/26/2015	10:58	Field Sample	Ground	Main Building, Office #2, 1' North, 4' West from SE corner on a shelf
C003-AAP015-01	2430455	1.4	+/- 0.2	10/23/2015	10:50	10/26/2015	10:55	Field Sample	Ground	Main Building, Office #3, 5' North, 1.7' East from SW corner on a file cabinet
C003-AAP016-01	2430456	1.4	+/- 0.2	10/23/2015	11:40	10/26/2015	11:42	Field Sample	Ground	Main Building, Showroom #3, 50' from North wall and 2' from East wall on shelf
C003-AAP016-02	2430454	1.2	+/- 0.2	10/23/2015	11:40	10/26/2015	11:43	Field Duplicate	Ground	Main Building, Showroom #3, 45.4' North, 6' East from SW corner on PEI stand
C003-AAP017-01	2430530	1.5	+/- 0.2	10/23/2015	10:53	10/26/2015	10:57	Field Sample	Ground	Main Building, Office #1, 5.8' West, 1' South from NE corner on a shelf
C003-AAP018-01	2430446	0.5	+/- 0.2	10/23/2015	11:02	10/26/2015	11:23	Field Sample	Ground	Main Building, Receiving Area, 11.7' North, 3' West from SE corner on wood shelf
C003-AAP019-01	2430431	0.6	+/- 0.2	10/23/2015	10:59	10/26/2015	11:22	Field Sample	Ground	Main Building, Receiving Area, 5.3' East, 3.7' South from NW corner on steel shelf
C003-AAP020-01	2430516	0.9	+/- 0.2	10/23/2015	10:09	10/26/2015	10:42	Field Sample	Second	Main Building, Showroom #4, 13.2' West, 11.8' South from NE corner on PEI stand
C003-AAP021-01	2430443	1.0	+/- 0.2	10/23/2015	10:03	10/26/2015	10:40	Field Sample	Second	Main Building, Conference Room, On top of the glass table
C003-AAP022-01	2430442	0.8	+/- 0.2	10/23/2015	9:56	10/26/2015	10:37	Field Sample	Second	Main Building, Office #5, On top of a countertop middle of North side
C003-AAP023-01	2430474	0.9	+/- 0.2	10/23/2015	9:58	10/26/2015	10:39	Field Sample	Second	Main Building, Office #4, On top of wood base cabinet on NE corner
C003-AAP024-01	2430517	0.7	+/- 0.2	10/23/2015	9:51	10/26/2015	10:35	Field Sample	Second	Main Building, Lobby #4, 6' East, 1.8' North from SW corner on a metal file cabinet
C003-AAP025-01	2430452	0.7	+/- 0.2	10/23/2015	9:36	10/26/2015	10:31	Field Sample	Second	Main Building, Reception Area, 3' North, 1.3' West from SE corner on countertop
C003-AAP026-01	2432022	0.6	+/- 0.2	10/23/2015	9:41	10/26/2015	10:33	Field Sample	Second	Main Building, Office #6, 6.2' West, 5.5' South from NE corner on a desk
C003-AAP026-02	2430465	0.6	+/- 0.2	10/23/2015	9:42	10/26/2015	10:33	Field Duplicate	Second	Main Building, Office #6, 6.6' West, 5.5' South from NE corner on a desk
C003-AAP027-01	2430467	0.7	+/- 0.2	10/23/2015	10:16	10/26/2015	10:44	Field Sample	Second	Main Building, Room #2, On top of a cabinet in the middle of the room
C003-AAP028-01	2430413	0.7	+/- 0.2	10/23/2015	10:24	10/26/2015	10:46	Field Sample	Second	Main Building, Architect's Office - Back Room, 9' 7" from North wall and 14' 6" from East wall
C003-AAP029-01	2430531	0.7	+/- 0.2	10/23/2015	10:39	10/26/2015	10:49	Field Sample	Second	Main Building, Room #3, 22' 4" from South wall and 14' from East wall
C003-AAP030-01	2430451	2.9	+/- 0.2	10/23/2015	10:45	10/26/2015	10:53	Field Sample	Ground	Main Building, Mechanical/Electrical Room, 2' from South wall and 4' from West wall
FB01-100915	2430525	0.1	+/- 0.1	10/23/2015	11:37	10/26/2015	11:40	Field Blank	Ground	Main Building, Showroom #3, 18.3' North, 3.8' West from SE corner of a shelf
FB02-100915	2430481	0.1	+/- 0.3	10/23/2015	9:46	10/26/2015	10:34	Field Blank	Second	Main Building, Office #6, 2.1' West, 0.9' South from NE corner on a shelf

Notes:

pCi/L - picocuries per liter.

Std. Dev. - Standard Deviation.

PEI - Precision Environmental, Inc.